

## Photo/Contact Tachometer Model R7140



## **Features**

- Dual function unit with both contact and non-contact capabilities
- Provides fast and accurate RPM measurements of rotating objects and surface speed measurements MPM (meter per min) and FPM (feet per min)
- Internal memory holds last reading for 5 mins and recalls min/max and last value
- LCD Display reverses depending on measurement mode
- Includes reflective tape, large and small cone tip adapters, funnel adapter, wheel adapter, batteries, and hard carrying case

## **Specifications**

RPM Range (Contact): 0.5 to 19,999 RPM Range (Photo): 5 to 99,999

Surface Speed Range: 0.05 to 1,999.9m/min

0.2 to 6,560ft/min

Resolution: Photo: O.1 RPM (≤999.9)

1 RPM (>1000)

Contact: 0.1 RPM (≤999.9)

1 RPM (>1000)

Surface: 0.1m/min (≤99.99)

0.1ft/min (<99.99)
1ft/min (>1000)

Basic Accuracy:  $\pm (0.05\% + 1 \text{ dgt.})$ 

**General Specifications** 

Visible Indicator: Yes (Light)

Target Distance: 1.0ft (300mm) (Photo)

Response Time: <1 second

Sampling Time: Photo: 1 second (over 60 RPM)

Contact: 1 second (over 6 RPM)

Display Size/Type: 5 Digit LCD Display

Auto Shut Off: Yes

Internal Memory: Max, Min and Last

Low Battery Indicator: Yes

Power Supply: 4 x AA Batteries

Product Certifications: CE

Dimensions:

Operating Temperature: 32 to 122°F (O to 50°C)
Storage Temperature: -4 to 140°F (-20 to 60°C)

Operating Humidity: 10 to 90%

8.5 x 2.6 x 1.5"

(215 x 65 x 38mm)

Weight: 10.6oz (300g)

## TECHNICAL DATA





Model	Description
R7140	Photo/Contact Tachometer
AS-35C	Replacement Measuring Wheel
CONE	Replacement Cone Tip
FUNNEL	Replacement Funnel Tip
EXT-SHAFT	Replacement Extension Shaft
RT100	Reflective Tape
CA-05A	Soft Carrying Case
R9940	Hard Shell Carrying Case
R7140-NIST	Photo/Contact Tachometer & NIST