

Model R2222

Stainless Steel Digital Stem Thermometer



Instruction Manual

Features

- Stainless steel 4.65" (118mm) stem
- · Easy-to-read LCD display
- User selectable °C/°F
- · Max/Min and data hold functions
- · Auto shut off
- Includes protective probe cover and battery

Specifications

Measuring Range: -40 to 482°F (-40 to 250°C)

Accuracy: $\pm 1.5\%$ of reading $+2^{\circ}$

Resolution: 0.1°F/°C

Type: Stem
Response Time: 2 secs

Stem Material: Stainless Steel

Stem Length: 4.65" (118mm)
Display: 3 1/2-digit LCD

Data Hold: Yes

Max: Yes

Auto Shut-off: Yes (after 20 mins)
Power Supply: 1 x LR44 battery

Product Certifications: CE

Dimensions: 8.3 x 1.3 x 0.8" (211 x 32 x 19mm)

Weight: 1.2oz (35g)



Operating Instructions

To use the thermometer, remove the protective sheath, press the **ON/OFF** button and insert at least 1/2 of the stem into the testing area. The current temperature will be displayed. To save the battery life, the thermometer will automatically turn off after approximately 20 minutes.

Changing °F to °C

The temperature unit can be changed from Fahrenheit to Celsius by pressing the °C/°F button.

Hold Current Temperature

Press the **MODE** button once and "Hold" will appear on the display. To return to normal mode, press the **MODE** button three more times.

Recall Highest/Lowest Temperatures

To recall the highest temperature, press the **MODE** button twice and "MAX" will appear on the display. Press once more to recall the lowest temperature and "MIN" will appear on the display.

For service or information on this or any other REED product, contact REED Instruments at info@reedinstruments.com.



Notes			



sales@GlobalTestSupply.com